

Vehicle Inspection Report

This vehicle has  **PASSED**

The AA has fully inspected this vehicle, covering:

- | | |
|--|-----------------------------------|
| ✓ Body exterior fittings | ✓ Road test |
| ✓ Engine compartment | ✓ Interior fitting |
| ✓ Electrical controls | ✓ Rear suspension and under frame |
| ✓ Interior and luggage compartment | ✓ Transmission and Final Drive |
| ✓ Front suspension, steering and under frame | ✓ Brakes |
| ✓ Exhaust system | ✓ Wheels and tyres |
| ✓ Fuel system | |

Road tested for

5 miles on 31 January 2024

Registration number

KN66KVG

By a certified AA vehicle engineer

Dealer's Name **Mylson** Inspection Number: **BVI733926** Status: **PASS**

Registration: **KN66KVG** Mileage at start of inspection: **41640**

Make: **MERCEDES-BENZ** Colour: **SILVER**

Model: **C 250 AMG LINE D AUTO** VIN **WDD2053082F451140**

Ramp Available: **Yes** Fuel Type **Diesel**

Key for points in following sections

P Pass

F Fail

A Advisory

N/A Not applicable

Please note:
Right = Offside (O/S)
Left = Nearside (N/S)
as viewed from the driver's seat.

Body Exterior Fittings:

Bonnet Catch	P	Bonnet Hinges	P
Door Locks and Operation	P	Fuel Filler Cover/Flap	P
Panoramic Roof	N/A	Registration Plates	P
Sunroof/Convertible Operation	N/A	Windscreen and Glass	P

Interior Fittings:

Air Vents and Operation	P	Boot/Tailgate Lock and Operation	P
Mirrors	P	Roof Blind Condition and Operation	N/A
Seat Adjustment	P	Seatbelts	P

Engine Compartment:

Abnormal Noises	P	Antifreeze Strength	P
Auxiliary Drive Belts	P	Brake Fluid Level	P
Clutch Fluid Level	N/A	Coolant Cap	P
Coolant Leaks	P	Coolant Level and Condition	P
Engine Mountings	P	Engine Oil Level	P
Excessive Fumes/Smoke	P	Fuel Pipes	P

Hoses/Pipes Condition	P	Idle Speed	P
Oil/Fluid Leak(s)	P	Power Steering Fluid Level	N/A
Turbo/Supercharger Abnormal Noise/Leaks	P		

Electrical System and Controls:

Air Condition Operation	P	Auto Stop Start Function	P
Auxiliary Lights	P	12V Battery visual condition	P
Brake Lights	P	Controls/Switches	P
Fog Lights	P	Headlamp Washers	N/A
Headlights	P	Horn	P
Indicator/Hazard Lights	P	Instruments	P
Interior Lights	P	Number Plate Lights	P
Panel Lights	P	Reverse Lights	P
Side/Running Lights	P	Start Button/Ignition Lock	P
Window Operation	P	Wipers and Washers	P

Front Suspension, Steering and Underbody:

Anti-Roll Bar and Links	P	Engine Underside Leakage	P
Power Steering Operation	P	Shock Absorbers Condition/Leaks	P
Springs/Suspension Units	P	Steering and Ball Joint	P
Steering Pipes/Hoses	P	Steering Rack Gaitors	P
Steering Rack/Box	P	Subframe Condition/Mountings	P
Suspension Arms/Bushes	P	Underbody Condition	P
Wheel Hubs/Bearings	P		

Rear Suspension and Underbody:

Anti-Roll Bar and Links	P	Engine Underside Leakage	P
-------------------------	---	--------------------------	---

Shock Absorbers Condition/Leaks	P	Springs/Suspension Units	P
Subframe Condition/Mounting	P	Suspension Arms/Bushes	P
Underbody Condition	P	Wheel Hubs/Bearings	P

Transmission/Final Drive:

Casings Condition	P	Clutch Hydraulic System	N/A
Clutch Operation	N/A	Driveshaft Assembly	P
Front CV Boots	P	Gear Linkage Operation (wear)	P
Mountings	P	Oil/Fluid Leaks	P
Propshaft	P	Propshaft Bearings/Supports	P
Rear CV Boots	P	Universal Joints	P
Abnormal Noises	P		

Exhaust:

Catalytic Converter(s) Condition	N/A	Diesel Particulate Filter	P
Heat Shields/Mountings	P	Joints/Couplings	P
Manifold Condition	P	Pipes Condition	P
Silencer(s)	P		

Fuel System:

Breather Pipes	P	Evidence of Leaks	P
Fuel Lines	P	Tank	P
Tank Fixings	P		

Brakes:

Brake Pedal Operation	P	Brake Pipes	P
Discs/Pads (if visible)	P	Flexible Hoses	P
Fluid Leaks	P	Handbrake Operation	P

Pedal and Pad/Linkage	P	Servo/Power Assistance	P
-----------------------	---	------------------------	---

Wheels and Tyres:

Front Left Damage	P	Front Right Damage	P
-------------------	---	--------------------	---

Rear Left Damage	P	Rear Right Damage	P
------------------	---	-------------------	---

Spare Damage	N/A	Locking Wheel Key Present	P
--------------	-----	---------------------------	---

Onward Travel	P		
---------------	---	--	--

Road Test:

Auto Changes/Kickdown	P	Auto Gearbox Park Function	P
-----------------------	---	----------------------------	---

Auto Gearbox Sports Function	P	Brakes (Vibration/Noise)	P
------------------------------	---	--------------------------	---

Cruise Control	P	Engine Noise (Abnormal)	P
----------------	---	-------------------------	---

Engine Performance	P	Exhaust Smoke	P
--------------------	---	---------------	---

General Steering/Handling	P	Hot Restarting	P
---------------------------	---	----------------	---

Instrument Control/Function	P	Overheating Evidence	P
-----------------------------	---	----------------------	---

Paddle Controls	P	Parking Sensors	P
-----------------	---	-----------------	---

Road Holding/Stability	P	Steering Effort	P
------------------------	---	-----------------	---

Suspension Noise	P		
------------------	---	--	--

Warning Lights:

Warning Lights	P		
----------------	---	--	--

Other:

Other Item	P		
------------	---	--	--

Wheels & Tyres

Position	Manufacturer	Tyre Width	Profile	Wheel Size	Speed Rating	Wheel Type	Tread (mm)
Left Front	Other	225	40	19	W	Alloy	5
Right Front	Other	225	40	19	W	Alloy	6
Left Rear	Other	255	35	19	W	Alloy	3
Right Rear	Other	255	35	19	W	Alloy	4
Spare							

Road Test

Test distance: **5 miles**

Speed achieved up to: **50 mph**

Dealer's Name

Mylson

Date

31 January 2024

Rectification Required:

Advisories
